



Crown Molding



MATERIAL LIST MOLDINGS

Crown Molding

Inside Side (2)	$1/2'' \times 2'' \times 19\frac{1}{8}''$
Middle Side (2)	$1\frac{1}{16}'' \times 1\frac{5}{16}'' \times 19\frac{3}{16}''$
Outside Side (2)	$9/16'' \times 9/16'' \times 20\frac{3}{8}''$
Inside Front (1)	$1/2'' \times 2'' \times 34''$
Middle Front (1)	$1\frac{1}{16}'' \times 1\frac{5}{16}'' \times 35\frac{5}{16}''$
Outside Front (1)	$9/16'' \times 9/16'' \times 36\frac{7}{16}''$

Waist Molding

T x W x L

Inside Side (2)	$1/4'' \times 1\frac{1}{8}'' \times 18\frac{5}{8}''$
Inside Front (1)	$1/4'' \times 1\frac{1}{8}'' \times 33\frac{3}{4}''$
Outside Side (2)	$7/8'' \times 1'' \times 19\frac{5}{8}''$
Outside Front (1)	$7/8'' \times 1'' \times 35\frac{5}{8}''$

Waist Molding

